COLORADO

```
ROCKY MOUNTAIN METROPOLITAN (BJC)(KBJC)
                                                                                                         DENVER
                                                9 NW UTC-7(-6DT) N39°54.53
                                                                                                  H-3F. 5A. L-10F. A
  W105007 03
  5673 B ARFF Index—See Remarks NOTAM FILE BJC
                                                                                                          IAP, AD
  RWY 12L-30R: H9000X100 (ASPH-GRVD) S-65, D-105, 2S-95,
    2D-150 PCN 31 F/D/W/T HIRL
    RWY 12L: REIL. PAPI(P4L)-GA 3.0° TCH 41'. 1.0% down.
    RWY 30R: MALSR, PAPI(P4L)-GA 3.0° TCH 52', Rgt tfc, 1.1% up,
                                                                       Golf
  RWY 12R-30L: H7002X75 (ASPH-GRVD) S-12.5 MIRL
                                                                                        = 2
                                                                              Course
    1.1% up NW
    RWY 12R: REIL, PAPI(P2L)-GA 3.0° TCH 40', Rgt tfc.
    RWY 30L: REIL. PAPI(P2L)-GA 3.0° TCH 41'.
  RWY 03-21: H3600X75 (ASPH) S-40, D-45, 2D-65 MIRL
    0.4% up S
    RWY 03: PAPI(P2L)-GA 3.0° TCH 30'.
    RWY 21: PAPI(P2L)-GA 3.0° TCH 40'. Rgt tfc.
  RUNWAY DECLARED DISTANCE INFORMATION
    RWY 03: TORA-3600 TODA-3600 ASDA-3600 LDA-3600
                                                                                       Go
    RWY 12L:TORA-9000 TODA-9000 ASDA-9000 LDA-9000
                                                                                      Ca
                                                                          1
    RWY 12R: TORA-7002 TODA-7002 ASDA-7002 LDA-7002
                                                                     Residential
    RWY 21: TORA-3600 TODA-3600
                                     ASDA-3600
                                                   I DA-3600
                                                                      Area
    RWY 30L:TORA-7002 TODA-7002 ASDA-7002 LDA-7002
                                                                                     Residential Arec
    RWY 30R:TORA-9000 TODA-9000 ASDA-9000 LDA-9000
  SERVICE: S4 FUEL 100LL, JET A 0X 1, 2, 3, 4 LGT When twr closed ACTIVATE MIRL Rwy 03-21, and Rwy 12R-30L,
    HIRL Rwy 12L-30R, MALSR Rwy 30R, PAPI Rwy 03, Rwy 21, Rwy 12L, Rwy 12R, Rwy 30L, and Rwy 30R and REIL
    Rwy 12L, Rwy 12R and Rwy 30L-CTAF.
  AIRPORT REMARKS: Attended continuously. 100LL self svc. Birds and other wildlife on and invof rwys. Watch for wildlife on or
    near rwys. Helicopters arr/dep from rwys and twys. Pilots are requested to avoid flt over Standley Lake blo 8000' MSL.
    Jeffco VOR 150° 3.0 DME due to nesting eagles. Class II ARFF Index A, 24 hr PPR for unscheduled air carrier ops with
    more than 30 passengers seats call 720-352-0395. ARFF Index B also avbl PPR ctc arpt 720-352-0395. Voluntary
    noise abatement procedure in effect ctc noise office 303-271-4850. U.S. Customs user fee arpt. Twy C1 and Twy D only
    marked with reflectors. North terminal ramp slope exceeds FAA recommended stds, Flight Notification Service (ADCUS)
    avbl. NOTE: See Special Notices-Extensive Helicopter Flight Training. USAF 306 FTG Flight Training Areas, Vicinity of
    Colorado Springs and Pueblo Colorado.
  AIRPORT MANAGER: (303) 271-4851
  WEATHER DATA SOURCES: AWOS-3 (720) 887-8067
  COMMUNICATIONS: CTAF 118 6 ATIS 126 25 303-466-8744
    DENVER APP/DEP CON 126 1
```

```
METRO TWER 118.6 (300–0500Z‡) GND CON 121.7 CLNC DEL 132.6

AIRSPACE: CLASS D svc 1300–0500Z‡ other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE BJC.

JEFFC0 (H) VORW/DME 115.4 BJC Chan 101 N39°54.78 ' W105°08.34 ' 093° 1.0 NM to fld. 5737/11E.

VOR portion unusable:

226°-245° byd 36 NM bio 17,000'

246°-278° byd 30 NM bio 19,000'

279°-300° byd 34 NM bio 18,000'

DME unusable:

246°-278° byd 30 NM

ILS 111.7 I–BJC Rwy 30R. Class IA. Unmonitored when ATCT closed.

COMM/NAV/WEATHER REMARKS: Emerg frequency 121.5 not avbl at twr.
```

```
      DOVE CREEK
      (8V6)
      1 E
      UTC-7(-6DT)
      N37°45.89' W108°53.32'
      DENVER

      6975
      TPA—7700(725)
      NOTAM FILE DEN
      RWY 01-19: 4200X50 (DIRT)
      1.0% up S

      RWY 01: Fence.
      RWY 19: Road.
      RMRRKS: Unattended. Arpt CLOSED when snow covered. Rwy 01–19 has –3' ditch along both sides rwy. Rwy 01
      19 soft when wet. Rwy 01–19 rodent holes throughout. Unlimited vehicle use on arpt. Rwy 19 +12' ground 258' right of centerline parallel to extended centerline first 500'.

      AIRPORT MANAGER: 970-677-2282
      COMMUNICATIONS: CTAF 122.9
```

```
DOVE CREEK N37°48.52′ W108°55.88′ NOTAM FILE DEN.
(H) VORTACW 114.6 DVC Chan 93 277° 20.8 NM to Monticello. 6990/14E.
RCO 122.5 (DENVER RADIO)
```

DENVER H-3D. L-9D