134 FLORIDA

KISSIMMEE GATEWAY (ISM)(KISM) 16 SW UTC-5(-4DT) N28°17.39′ W81°26.23′

82 B TPA-See Remarks NOTAM FILE ISM

RWY15-33: H6001X100 (ASPH-GRVD) S-114, D-189, 2S-95,

2D-300 PCN 45 F/A/X/T MIRL

RWY 15: MALSF. PAPI(P4L)-GA 3.0° TCH 51'. Tree. Rgt tfc.

RWY 33: PAPI(P4L)-GA 3.0° TCH 45'. Tree.

RWY 06-24: H5001X100 (ASPH-GRVD) S-89, D-140

PCN 39 F/A/X/T MIRL

RWY 06: REIL. PAPI(P4L)—GA 3.0° TCH 45'. Trees. Rgt tfc.

RWY 24: REIL, PAPI(P4L)—GA 3.0° TCH 45', Pole.

SERVICE: S4 FUEL 100LL, JET A 0X1 LGT MIRL Rwy 15–33 and Rwy 06–24 preset low ints dusk-0300Z‡, to incr ints and ACTIVATE after 0300Z‡—CTAF. ACTIVATE MALSF Rwy 15, PAPI Rwy 06, Rwy 15, Rwy 24 and Rwy 33—CTAF.

AIRPORT REMARKS: Attended 1200–1500Z‡. Arpt CLOSED to ultralgt acft exc by prior permission from arpt mgr. Birds invof arpt. Be on the lookout for coyotes and deer on afld. Noise sensitive area 1/2 mile north of AER 24. Rwy 06 holding bay rstd to acft with wingspan of 49′ or less. No early turnouts on Rwy 06 dep. Req all jets/turbo props use NBAA close–in procedures. Rwy 15 is preferred calm wind rwy. TPA for let acft 918′ AGL, turboprop and jet acft 1418′ AGL. No helicopter run on landings permitted.

AIRPORT MANAGER: (407) 518-2516

WEATHER DATA SOURCES: AWOS-3PT 128.775 (407) 847-0533.

COMMUNICATIONS: CTAF 124.45 ATIS 128.775 UNICOM 122.95

® ORLANDO APP/DEP CON 119.4 CLNC DEL 119.95 (when twr clsd)

TOWER 124.45 (1200-0300Z‡) GND CON 121.7 CLNC DEL 121.7

AIRSPACE: CLASS D svc 1200-0300Z‡ other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE ORL.

TACAN AZIMUTH unusable:

066°-084°

246°-289° byd 17 NM blo 2,000°

246°-289° byd 28 NM blo 2,500′

ILS/DME 109.75 I–ISM Chan 34(Y) Rwy 15. Unmonitored.

ORLANDO SPB (FL5) 12 NW UTC-5(-4DT) N28°37.27′ W81°38.35′

JACKSONVILLE

JACKSONVILLE

IAP, AD

H-8H, L-21D, 24F

66 NOTAM FILE PIE Not insp.

WATERWAY 13W-31W: 5000X500 (WATER)

SERVICE: S2 FUEL 100LL, JET A, MOGAS

SEAPLANE REMARKS: All ops are conducted in VFR weather conditions. The landing area is limited to public use. Public use SPB owners request prior knowledge of any and all arrivals to best prepare for mooring, handling and fueling, 407–331–5655 or 386–248–2010.

AIRPORT MANAGER: 407-331-5655 COMMUNICATIONS: CTAF 122.9

Residential Area